

November 15, 2007

RE: WMH TOOL GROUP

FCC ID: VSVOAVTP06

I have a few comments on this application. Depending on your responses, kindly understand there may be additional comments.

- 1. It seems the schematic is short of RF circuit. Please update us revised schematic with RF circuit.
- 2. Please provide an operational description.
- Please correct the applicant name shown at page 1,2,4,5 of test report. It should be "WMH TOOL GROUP".

George Chen Chief Technical Officer - Asia

mailto:george@atcb.com

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.