Test report No. : 11339636H-A-R1
Page : 52 of 54
Issued date : January 30, 2017
FCC ID : VTLCMA219

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 11339636H-A-R1
Page : 53 of 54
Issued date : January 30, 2017
FCC ID : VTLCMA219

Radiated Spurious Emission




Photo 1





Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 11339636H-A-R1
Page : 54 of 54
Issued date : January 30, 2017
FCC ID : VTLCMA219

Worst Case Position (Horizontal: X-axis/ Vertical: Y-axis)







End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124