



#### **Appendix A. Test Photos**

1. Photographs of Conducted Emissions Test Configuration

Mode 3



Front view



Rear view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A8

Report Version







Side view


SPORTON INTERNATIONAL INC. Page No. : A2 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973





# 2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A3 of A8

Report Version




FCC Test Report

Report No. : FR581906-02AC

## For radiated emissions 30MHz~1GHz Mode 1



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A8


Report Version



#### FCC Test Report

Report No. : FR581906-02AC

### For radiated emissions above 1GHz Mode 1



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A8

Report Version





Mode 2



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A6 of A8

Report Version






Mode 3



Front view



Rear view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A7 of A8


Report Version







EUT close up photo Front view



EUT close up photo Rear view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A8 of A8

Report Version







EUT close up photo

SPORTON INTERNATIONAL INC. Page No. : A9 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973