



## **Appendix A. Test Photos**

1. Photographs of Conducted Emissions Test Configuration Mode 3



Front view



Rear view

SPORTON INTERNATIONAL INC. Page No. : A1 of A8 TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973







Side view


SPORTON INTERNATIONAL INC. Page No. : A2 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973






## 2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



Rear view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A3 of A8


Report Version



## For radiated emissions 30MHz~1GHz Mode 3



Front view



: A4 of A8

: Rev. 01

Rear view

SPORTON INTERNATIONAL INC. Page No. TEL: 886-3-327-3456 Report Version


FAX: 886-3-327-0973




FCC Test Report

Report No.: FR581906-02AN

## For radiated emissions above 1GHz Mode 1



Front view



Rear view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A8 Report Version : Rev. 01





Mode 2



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A6 of A8

Report Version






Mode 3



Front view



Rear view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A7 of A8


Report Version







EUT close up photo



EUT close up photo

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A8 of A8

Report Version