



Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A8

Report Version :

: Rev. 02

Report No.: FR581906AC





Report No. : FR581906AC




Side view

SPORTON INTERNATIONAL INC. Page No. : A2 of A8
TEL: 886-3-327-3456 Report Version : Rev. 02





2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Report No.: FR581906AC

Front view



Rear view


SPORTON INTERNATIONAL INC. Page No. : A3 of A8 TEL: 886-3-327-3456 Report Version : Rev. 02




FCC Test Report

Report No.: FR581906AC

For radiated emissions 30MHz~1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A8 : Rev. 02

Report Version




FCC Test Report

Report No.: FR581906AC


: A5 of A8

: Rev. 02

For radiated emissions above 1GHz Mode 1



Front view



Rear view


SPORTON INTERNATIONAL INC. Page No. TEL: 886-3-327-3456 Report Version





Report No.: FR581906AC

Mode 2



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A6 of A8

Report Version


: Rev. 02






Report No.: FR581906AC

Mode 3



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A7 of A8


Report Version

: Rev. 02






Report No.: FR581906AC



EUT took a close view



EUT took a close view

SPORTON INTERNATIONAL INC. Page No. : A8 of A8
TEL: 886-3-327-3456 Report Version : Rev. 02