# **Appendix A. Test Photos**

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

## 1 Photographs of Conducted Emissions Test Configuration

Mode 2



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A2 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01




**SIDE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

## 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 




**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A4 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

For radiated emissions 30MHz~1GHz

Mode 2



**FRONT VIEW** 




**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A5 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

#### For radiated emissions above 1GHz

Mode 2



#### **FRONT VIEW**



### **REAR VIEW**

SPORTON INTERNATIONAL INC. Page No. : A6 of A6 TEL: 886-3-327-3456 Report Version : Rev. 01