

Report No.: FR281440AC

Appendix A. Test Photos

SPORTON INTERNATIONAL INC. Page No. : A1 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973



1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A2 of A7

Report Version

: Rev. 01

Report No.: FR281440AC





Report No.: FR281440AC



SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A7 TEL: 886-3-327-3456 Report Version : Rev. 01


FAX: 886-3-327-0973





2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



Report No.: FR281440AC

: A4 of A7

: Rev. 01

FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version


FAX: 886-3-327-0973




FCC RADIO TEST REPORT

Report No.: FR281440AC

For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A7

Report Version


: Rev. 01




FCC RADIO TEST REPORT

Report No.: FR281440AC

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A6 of A7

Report Version


: Rev. 01




FCC RADIO TEST REPORT

Report No.: FR281440AC

EUT take a close-up



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A7 of A7

Report Version

: Rev. 01