

FCC RADIO TEST REPORT

APPENDIX B. Photographs of EUT





Report No. : FR281437



TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B1 OF B11
ISSUED DATE : Nov. 20, 2012







TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B2 OF B11
ISSUED DATE : Nov. 20, 2012







TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B3 OF B11
ISSUED DATE : Nov. 20, 2012



FCC RADIO TEST REPORT





Report No. : FR281437



TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B4 OF B11 ISSUED DATE : Nov. 20, 2012










TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B5 OF B11 ISSUED DATE : Nov. 20, 2012












TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B6 OF B11
ISSUED DATE : Nov. 20, 2012







TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B7 OF B11
ISSUED DATE : Nov. 20, 2012





06 08 01 08 06 04 06 23 01 001 06 08 01 09 05 07 08 05 01


SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B8 OF B11
ISSUED DATE : Nov. 20, 2012

Report No. : FR281437








TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B9 OF B11
ISSUED DATE : Nov. 20, 2012








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B10 OF B11

ISSUED DATE : Nov. 20, 2012









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B11 OF B11

ISSUED DATE : Nov. 20, 2012