



Appendix A. Test Photos1. Photographs of Conducted Emissions Test Configuration



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A5


Report Version

: Rev. 01









SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report V


FAX: 886-3-327-0973

Page No. : A2 of A5
Report Version : Rev. 01






2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



: A3 of A5

: Rev. 01

Rear view


SPORTON INTERNATIONAL INC. Page No. TEL: 886-3-327-3456 Report Version

FAX: 886-3-327-0973





For radiated emissions 30MHz~1GHz for Non-Beamforming



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A5


Report Version

: Rev. 01






For radiated emissions 30MHz~1GHz for Beamforming



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A5


Report Version

: Rev. 01






For radiated emissions above 1GHz for Non-Beamforming



Front view



Rear view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A6 of A5 Report Version : Rev. 01






For radiated emissions above 1GHz for Beamforming



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A7 of A5 Report Version : Rev. 01