



Report No.: FR660601AC

Appendix A. Test Photos1. Photographs of Conducted Emissions Test Configuration



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A5


Report Version

: Rev. 01





Report No.: FR660601AC



Side view


SPORTON INTERNATIONAL INC. Page No. : A2 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973





2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz




Report No.: FR660601AC

: A3 of A5

: Rev. 01

Front view



Rear view

SPORTON INTERNATIONAL INC. Page No. TEL: 886-3-327-3456 Report Version


FAX: 886-3-327-0973



FCC Test Report

Report No.: FR660601AC

For radiated emissions 30MHz~1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A5 Report Version : Rev. 01



FCC Test Report

Report No.: FR660601AC

For radiated emissions above 1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A5

Report Version

: Rev. 01