


Test Report No. : FR231932A

## Appendix B. Setup Photographs

## <Conducted Emission>




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VUIPDS4330LB Page Number : B1 of B2
Report Issued Date : Apr. 13, 2012
Report Version : Rev. 01




## <Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VUIPDS4330LB Page Number : B2 of B2 Report Issued Date : Apr. 13, 2012 Report Version : Rev. 01

Report No.: FR231932A