


FCC Test Report



**Report No. : FR512732** 




SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page Number : B3 of B13
Report Version : Rev. 01










SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page Number : B4 of B13 Report Version : Rev. 01











SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page Number : B5 of B13 Report Version : Rev. 01











Page Number : B6 of B13 Report Version : Rev. 01











Page Number : B7 of B13 Report Version : Rev. 01










Page Number : B8 of B13 Report Version : Rev. 01










SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page Number : B9 of B13
Report Version : Rev. 01











Page Number : B10 of B13 Report Version : Rev. 01











Page Number : B11 of B13 Report Version : Rev. 01










Page Number : B12 of B13
Report Version : Rev. 01



FCC Test Report



TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page Number : B13 of B13 Report Version : Rev. 01