


Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VUIPDT4330LB Page Number : B1 of B2
Report Issued Date : Apr. 30, 2012
Report Version : Rev. 01


Report No.: FR232266B



Report No.: FR232266B

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VUIPDT4330LB Page Number : B2 of B2
Report Issued Date : Apr. 30, 2012
Report Version : Rev. 01