



## FCC RADIO TEST REPORT

## APPENDIX B. Photographs of EUT



**Report No. : FR272809** 



TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B1 OF B7

ISSUED DATE : Oct. 23, 2012










SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B2 OF B7

ISSUED DATE : Oct. 23, 2012









TEL: 886-3-327-3456 FAX: 886-3-327-0973








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B4 OF B7
ISSUED DATE : Oct. 23, 2012










SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B5 OF B7 ISSUED DATE : Oct. 23, 2012










TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B6 OF B7 ISSUED DATE : Oct. 23, 2012









TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B7 OF B7
ISSUED DATE : Oct. 23, 2012