











PAGE NUMBER : B3 of B15
Report Version : Rev. 02






























PAGE NUMBER : B6 of B15 Report Version : Rev. 02











PAGE NUMBER : B7 of B15
Report Version : Rev. 02












PAGE NUMBER : B8 of B15
Report Version : Rev. 02












PAGE NUMBER : B9 of B15
Report Version : Rev. 02













Report No. : EP430452-03





TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B11 of B15
Report Version : Rev. 02



Report No. : EP430452-03



TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B12 of B15 Report Version : Rev. 02