

Report No.: FR272809Al

Appendix A. Test Photos


SPORTON INTERNATIONAL INC. Page No. : A1 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973




Report No.: FR272809Al

1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A2 of A7

Report Version

: Rev. 01



FCC RADIO TEST REPORT

Report No.: FR272809AI



SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A7 TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973






Report No.: FR272809AI

: A4 of A7

: Rev. 01

2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version


FAX: 886-3-327-0973




FCC RADIO TEST REPORT

Report No.: FR272809AI

For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Particle 1886-3-327-3456 Re

FAX: 886-3-327-0973


Page No. : A5 of A7 Report Version : Rev. 01




FCC RADIO TEST REPORT

Report No.: FR272809AI

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A6 of A7

Report Version : Rev. 01






EUT take a close-up



Report No.: FR272809Al

FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A7 of A7
Report Version : Rev. 01