

Appendix D. Product Photos





Report No.: FA232266




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VUIPDT4330LB Page Number : D1 of D2
Report Issued Date : Apr. 30, 2012
Report Version : Rev. 01



Report No.: FA232266

Antenna Location:



Antenna	Length	Width
WLAN & Bluetooth Antenna <tx rx=""></tx>	0.3cm	0.15cm

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VUIPDT4330LB Page Number : D2 of D2
Report Issued Date : Apr. 30, 2012
Report Version : Rev. 01



Appendix E. Test Setup Photos





Report No.: FA232266

Bottom Face with Phantom 0 cm Gap

Secondary Landscape with Phantom 0 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VUIPDT4330LB Page Number : E1 of E1
Report Issued Date : Apr. 30, 2012

Report Version : Rev. 01