

Appendix D. Product Photos





Report No.: FA232266-05




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VUIPDT4330LBNFC Page Number : D1 of D2
Report Issued Date : May 04, 2012
Report Version : Rev. 01



Antenna Location:



Antenna	Length	Width
NFC Antenna <tx rx=""></tx>	10.0cm	1.0cm
WLAN & Bluetooth Antenna <tx rx=""></tx>	0.3cm	0.15cm

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VUIPDT4330LBNFC Page Number : D2 of D2
Report Issued Date : May 04, 2012
Report Version : Rev. 01

Report No.: FA232266-05



Appendix E. Test Setup Photos





Report No.: FA232266-05

Bottom Face with Phantom 0 cm Gap

Secondary Landscape with Phantom 0 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VUIPDT4330LBNFC Page Number : E1 of E1 Report Issued Date: May 04, 2012

Report Version : Rev. 01