






## Photographs of EUT







TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : 1 OF 11
ISSUED DATE : Jun. 22, 2016









Part No.: 1415-00XR000


















Part No.: 1415-00XS000






TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : 4 OF 11
ISSUED DATE : Jun. 22, 2016








Part No.: 1415-01AF000



TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : 5 OF 11
ISSUED DATE : Jun. 22, 2016











PAGE NUMBER : 6 OF 11
ISSUED DATE : Jun. 22, 2016





Part No.: 1415-01AE000






TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : 7 OF 11
ISSUED DATE : Jun. 22, 2016









Antenna 5 Part No.: 1415-0172000




SPORTON International Inc.











PAGE NUMBER : 9 OF 11
ISSUED DATE : Jun. 22, 2016






Part No.: 1415-0171000











PAGE NUMBER : 11 OF 11
ISSUED DATE : Jun. 22, 2016