




Report No.: FR512732-01

Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A6

Report Version

: Rev. 01







Report No.: FR512732-01

Side view


SPORTON INTERNATIONAL INC. Page No. : A2 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973




FCC Test Report Report No.: FR512732-01

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A3 of A6

Report Version


: Rev. 01




FCC Test Report

Report No. : FR512732-01

For radiated emissions 30MHz~1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. Report Version : A4 of A6 : Rev. 01




FCC Test Report

Report No.: FR512732-01

For radiated emissions above 1GHz



Front view



Rear view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A6 Report Version : Rev. 01





Report No. : FR512732-01



EUT take a close-up



EUT take a close-up

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A6 of A6 Report Version : Rev. 01