


Report No. : FG332221-07

## Appendix B. Setup Photographs


## <Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VUIMU736ARC0 Page Number : B1 of B2
Report Issued Date : Jul. 08, 2013
Report Version : Rev. 01




Report No.: FG332221-07

## **EUT with KEYBOARD COVER**

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VUIMU736ARC0 Page Number : B2 of B2
Report Issued Date : Jul. 08, 2013
Report Version : Rev. 01