

FCC Test Report No.: EP430452-02

APPENDIX B. Photographs of EUT





TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B1 OF B15
ISSUED DATE : Dec. 4, 2014







Report No.: EP430452-02



TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B2 OF B15
ISSUED DATE : Dec. 4, 2014



FCC Test Report No.: EP430452-02



TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B3 OF B15
ISSUED DATE : Dec. 4, 2014







Report No.: EP430452-02



SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B13 OF B15

ISSUED DATE : Dec. 4, 2014








Report No. : EP430452-02



TEL: 886-3-327-3456 FAX: 886-3-327-0973 ISSUED DATE : Dec. 4, 2014







Report No.: EP430452-02



SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B15 OF B15

ISSUED DATE : Dec. 4, 2014