Test Photos Report No. : FR350924

Appendix A. TEST PHOTOS

1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW




REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A1 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01



Report No.: FR350924



CLOSE VIEW




CLOSE VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01




2 Photographs of Radiated Emissions Test Configuration For radiated emission



Report No. : FR350924

FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A4 TEL: 886-3-327-3456 Report Version : Rev. 01



Report No.: FR350924



CLOSE VIEW



CLOSE VIEW

SPORTON INTERNATIONAL INC. Page No. : A4 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01