

FCC RADIO TEST REPORT

APPENDIX B. Photographs of EUT




Report No. : FR281440




SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B1 OF B17








TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B2 OF B17
ISSUED DATE : Nov. 20, 2012








TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B3 OF B17











TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B4 OF B17
ISSUED DATE : Nov. 20, 2012








TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B5 OF B17
ISSUED DATE : Nov. 20, 2012









TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B6 OF B17
ISSUED DATE : Nov. 20, 2012











TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B7 OF B17
ISSUED DATE : Nov. 20, 2012








TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B8 OF B17
ISSUED DATE : Nov. 20, 2012









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B9 OF B17
ISSUED DATE : Nov. 20, 2012










TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B10 OF B17








TEL: 886-3-327-3456 FAX: 886-3-327-0973










TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B12 OF B17









TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B13 OF B17









TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B14 OF B17








TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B15 OF B17







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B16 OF B17



FCC RADIO TEST REPORT



Report No. : FR281440

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B17 OF B17 ISSUED DATE : Nov. 20, 2012