

Report No. : FR461801AN

## **Appendix A. Test Photos**

SPORTON INTERNATIONAL INC. Page No. : A1 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01





1 Photographs of Conducted Emissions Test Configuration

Mode 1



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A2 of A7

Report Version

: Rev. 01

Report No.: FR461801AN






**SIDE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A3 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01




## 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 




**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A4 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01




For radiated emissions 30MHz~1GHz

Mode 1



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A7


Report Version : Rev. 01




FCC Test Report

Report No.: FR461801AN

## For radiated emissions above 1GHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A6 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01





EUT take a close-up

SPORTON INTERNATIONAL INC. Page No. : A7 of A7 TEL: 886-3-327-3456 Report Version : Rev. 01