



FCC RADIO TEST REPORT

APPENDIX B. Photographs of EUT




Report No.: FR281437





TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B1 OF B12
ISSUED DATE : Nov. 20, 2012











SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B2 OF B12 ISSUED DATE : Nov. 20, 2012