




Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A5

Report Version

: Rev. 01

**Report No. : FR512732** 



FCC Test Report No.: FR512732



Side view

SPORTON INTERNATIONAL INC. Page No. : A2 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973




FCC Test Report **Report No. : FR512732** 

## 2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A3 of A5

Report Version

: Rev. 01




FCC Test Report

Report No. : FR512732

## For radiated emissions 30MHz~1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A5

Report Version


: Rev. 01




## FCC Test Report

Report No. : FR512732

## For radiated emissions above 1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A5 Report Version : Rev. 01