

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VUI88651257 Page Number : B1 of B2
Report Issued Date : Jun. 10, 2015
Report Version : Rev. 01

Report No.: FR521701A

Report Template No.: BU5-FR15CBT Version 1.0




Report No. : FR521701A

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VUI88651257 Page Number : B2 of B2
Report Issued Date : Jun. 10, 2015
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.0