



## Appendix D. Product Photos




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VUIPDA4330LB Page Number : D1 of D2
Report Issued Date : Apr. 09, 2012
Report Version : Rev. 01

**Report No. : FA232172** 



Report No.: FA232172

## **Antenna Location:**



Antenna	Length	Width
WLAN / Bluetooth Antenna <tx rx=""></tx>	0.3cm	0.15cm

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VUIPDA4330LB Page Number : D2 of D2
Report Issued Date : Apr. 09, 2012
Report Version : Rev. 01



## Appendix E. Test Setup Photos







Report No.: FA232172

Secondary Landscape with Phantom 0 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VUIPDA4330LB Page Number : E1 of E1
Report Issued Date : Apr. 09, 2012

Report Version : Rev. 01