

1191 Northland Drive Mendota Heights, MN 55120 Suite 100

May 9, 2011

AmericanTCB 6731 Whittier Avenue Suite C110 McLean VA 22101

Attn: Director of Certification

Dear Sir or Madam

We, Healthsense Inc, 1191 Northland Drive, Suite 100, Mendota Heights, MN 55120 are requesting Limited Modular Approval (LMA) on the Gen 3.5 Modular Sensor Radio and hereby declare that the Gen 3.5 Modular Sensor Radio will only be integrated into Healthsense Inc. products. Therefore, Healthsense Inc. will retain full control of final installation

No manual exists for this product since Healthsense is the integrator. However, the following regulatory notices will be included in the end product manuals.

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

This device contains FCC ID: VUR100057

CAUTION: Changes or modifications not expressly approved by Healthsense Inc. could void the user's authority to operate the equipment.

In addition, the wording "Contains FCC ID: VUR100057" will be included on the label of the device in which the Gen 3.5 Modular Sensor Radio is installed.

Sincerely

Dean Anderson

Vice President of Engineering

Healthsense

1191 Northland Drive

Mendota Heights, MN 55120 Suite 100

800-576-1779