## ZHONG SHAN OCVACO TECHNOLOGY CO., LTD.

NO.142, SOUTH TANSHEN ROAD, TANZHOU TOWN, ZHONGSHAN, CHINA

FCC ID: VUX716TR

January 5, 2008

Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

I would like to confirm this device (FCC ID: VUX716TR) does not have tune up information because the tune up is fixed by the manufacturer. Therefore, the user cannot tune up the device.

Sincerely,

ZHONG SHAN OCVACO TECHNOLOGY CO., LTD.

Pingen Li Manager