
1. Photograph of the EUT


EUT: WWAN module (Ericsson AB / C5621)

Report No.: EP291115




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMC5621-D1 Page Number : 1 of 36
Report Issued Date : Oct. 05, 2012
Report Version : Rev. 01





Report No.: EP291115



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMC5621-D1

: 2 of 36 Page Number Report Issued Date : Oct. 05, 2012 Report Version : Rev. 01

EUT: WWAN module (Ericsson AB / C5621)

Report No.: EP291115




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMC5621-D1 Page Number : 3 of 36
Report Issued Date : Oct. 05, 2012
Report Version : Rev. 01

EUT: WWAN module (Ericsson AB / C5621)

Report No.: EP291115



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMC5621-D1 Page Number : 4 of 36
Report Issued Date : Oct. 05, 2012
Report Version : Rev. 01

2. External Photograph of the Host

Host: Tablet PC (Dell / Latitude 10 - ST2)

Report No.: EP291115



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMC5621-D1 Page Number : 5 of 36
Report Issued Date : Oct. 05, 2012
Report Version : Rev. 01

Report No.: EP291115



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMC5621-D1 Page Number : 6 of 36
Report Issued Date : Oct. 05, 2012
Report Version : Rev. 01

Photograph of Accessory for the Host 3.

Host: Tablet PC (Dell / Latitude 10 - ST2)

Report No.: EP291115

List of Accessory for Host (Notebook Computer):

- in a second of the second of		
Specification of Accessory		
AC Adapter	Brand Name	Dell
	Model Name	AA30NM131
Battery	Brand Name	Dell
	Model Name	FWRM8
WLAN Module	Brand Name	MITSUMI
	Model Name	DWM-W091

Remark: For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMC5621-D1 Page Number : 7 of 36 Report Issued Date : Oct. 05, 2012

Report Version : Rev. 01

Report No.: EP291115



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMC5621-D1 Page Number : 8 of 36
Report Issued Date : Oct. 05, 2012
Report Version : Rev. 01

Report No.: EP291115



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMC5621-D1 Page Number : 9 of 36
Report Issued Date : Oct. 05, 2012
Report Version : Rev. 01

Report No.: EP291115



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMC5621-D1 Page Number : 10 of 36 Report Issued Date : Oct. 05, 2012

Report Version : Rev. 01

Report No.: EP291115



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMC5621-D1 Page Number : 11 of 36
Report Issued Date : Oct. 05, 2012
Report Version : Rev. 01

Report No.: EP291115




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMC5621-D1 Page Number : 12 of 36
Report Issued Date : Oct. 05, 2012
Report Version : Rev. 01

Report No.: EP291115



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMC5621-D1 Page Number : 13 of 36
Report Issued Date : Oct. 05, 2012
Report Version : Rev. 01

Report No.: EP291115



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMC5621-D1 Page Number : 14 of 36
Report Issued Date : Oct. 05, 2012
Report Version : Rev. 01

Report No.: EP291115



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMC5621-D1 Page Number : 15 of 36
Report Issued Date : Oct. 05, 2012
Report Version : Rev. 01