



Appendix D - Product Photos





Report No.: CA020501-28







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 IC: 6317A-RTL8188CE Page Number : D1 of D1
Report Issued Date : Apr. 09, 2011
Report Version : Rev. 01



Appendix E - Test Setup Photos



Bottom of Laptop with Phantom 0 cm Gap (Sample 1)



Bottom of Laptop with Phantom 0 cm Gap (Sample 2)



Report No.: CA020501-28

Back of Panel with Phantom 2.5 cm Gap (Sample 2)

TEL: 886-3-327-3456 FAX: 886-3-328-4978 IC: 6317A-RTL8188CE Page Number : E1 of E1
Report Issued Date : Apr. 09, 2011

Report Version : Rev. 01