


## CH78 Hopping on mode (Upper) \_3Mbps





Report No.: BTL-FCCP-1-1802C015A Page 113 of 118





## CH00 (10 Harmonic of the frequency) \_3Mbps







Report No.: BTL-FCCP-1-1802C015A Page 114 of 118








## CH39 (10 Harmonic of the frequency) \_3Mbps



Report No.: BTL-FCCP-1-1802C015A Page 115 of 118








Report No.: BTL-FCCP-1-1802C015A


Page 116 of 118





## CH78 (10 Harmonic of the frequency) \_3Mbps






Report No.: BTL-FCCP-1-1802C015A Page 117 of 118







Report No.: BTL-FCCP-1-1802C015A Page 118 of 118