


www.tuv.com Appendix 3

Prüfbericht - **Nr.:** Test Report No.

02423092 001

Seite 1 von 3 Page 1 of 3



Module with Enclosure removed



Inner View of Enclosure




www.tuv.com Appendix 3

Prüfbericht - Nr.: Test Report No.

02423092 001

Seite 2 von 3 Page 2 of 3



Module with Enclosure



Bottom View of Module




www.tuv.com

Appendix 3


Prüfbericht - **Nr.:** Test Report No.

02423092 001

Seite 3 von 3 Page 3 of 3



RF Connector- Top View



RF Connector- Bottom View