


www.tuv.com Appendix 3

 Prüfbericht - Nr.: Test
 19660062 001
 Seite 1 von 2

 Report No.
 Page 1 of 2



RF Section- Transceiver with Shield Removed – Top View




www.tuv.com

Appendix 3


Prüfbericht - **Nr.:** Test Report No.

19660062 001

Seite 2 von 2 Page 2 of 2



RF Section- Transceiver with Shield Removed - Top View



RF Section- Transceiver – Bottom View