



Inside view EUT



Report no. ETLE100118.03, Page D1 of D8




Top side view of main board #1



Report no. ETLE100118.03, Page D2 of D8




Top side view of main board #1-1 (Open case)



Report no. ETLE100118.03, Page D3 of D8




Top side view of main board #1-2 (Open case)



Report no. ETLE100118.03, Page D4 of D8




Bottom side view of main board #1



Report no. ETLE100118.03, Page D5 of D8




Bottom side view of main board #1-1 (Open case)



Report no. ETLE100118.03, Page D6 of D8




Top side view of main sub board



Report no. ETLE100118.03, Page D7 of D8



Bottom side view of main sub board



Report no. ETLE100118.03, Page D8 of D8