



Inside view EUT



Report no. ETLE100108.17, Page D1 of D13



Top side view of main board #1




Report no. ETLE100108.17, Page D2 of D13



Appendix D. Internal Photographs

Top side view of main board #1-1 (Open case)




Report no. ETLE100108.17, Page D3 of D13

FCC ID: VWV-A-01-01A




Top side view of main board #1-2 (Open case)



Report no. ETLE100108.17, Page D4 of D13




Bottom side view of main board



Report no. ETLE100108.17, Page D5 of D13




Top side view of main sub board #1



Report no. ETLE100108.17, Page D6 of D13




Bottom side view of main sub board #1



Report no. ETLE100108.17, Page D7 of D13



Top side view of main sub board #2




Report no. ETLE100108.17, Page D8 of D13



Appendix D. Internal Photographs

Bottom side view of main sub board #2




Report no. ETLE100108.17, Page D9 of D13

FCC ID: VWV-A-01-01A




Top side view of RF board



Report no. ETLE100108.17, Page D10 of D13




Bottom side view of RF board



Report no. ETLE100108.17, Page D11 of D13




Top side view of LCD board



Report no. ETLE100108.17, Page D12 of D13



Bottom side view of LCD board



Report no. ETLE100108.17, Page D13 of D13