User's Guide for Multimedia Keyboard LK-7802

Installation of the keyboard

- 1. Please turn off your computer
- 2. Connect the keyboard with your computer's USB or PS/2 port
- 3. Start your computer

Installing Drivers

Install the driver attached under Windows 98/98SE as the following steps.

Step1. Insert the CD-ROM to the computer.

Step2. Double Click "Keyboard.exe".

Step3. Install the driver following the screen instruction

20 Hot keys function

Power: Turn off the computer directly.

Page Back: Back to the previous web page
Page Forward: Forward to next web page

Refresh: Update and refresh the content of present web page

Favorites: Open "My Favorited" folder

Sleep: Make computer into standby mode to decrease power consumption up to 70%

Play/Pause: Play or Pause an Audio or Video File.

Stop: Stop playing an audio or video file.

► Previous: Play the last track or watch the last clip played, in a series of audio or video files.

Next: Play the next audio or video

Mute: Cut the sound

WWW: Go to default home page

Search: Bring up "Search Windows" for Web

E-mail: Open the e-mail system My Computer: Call my computer Caculater: Open the Caculater

Word: Open one blank Windows Word file **Excel:** Open one blank Windows Excel file **Volume Knob:** Increase/Decrease the volume

Scroll Wheel: Page up/down

OFFICE HOTKEYS - Word/ Excel/ Scroll Wheel

will be activated in all Windows 98/98SE/2000/XP after driver installed.

Advice

Have a break after 30 minutes using the keyboard constinuously to preven any temporary or permanent injury on wist or another parts, which usually occurs after long period operation.

Warning

Any Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.