

# American Telecommunications Certification Body Inc.

6731 Whittier Ave, McLean, VA 22101

TO: Federal Communications Commission

RE: Request for placement into audit status for FCC ID: VXU-02AZ730D for supercede of manual

Please place this application in audit status so that we may supercede the original manual that was uploaded on Oct 27, 08, and a revised version uploaded on October 28, 08, with a newer version uploaded 1/10/09 that reflects some wording revisions, content did not change.

Wording revisions are:

#### 1. Page2 Additional sentence

#### At "3) Low battery alarm"

In addition, the battery (CR2032) used as the power supply for the U-WAVE-T has such a property that the battery voltage is abruptly restored in a period when the battery has been exhausted, if measurement data is consecutively transmitted at intervals of several seconds. In such cases, although low battery alarm errors are not output, the LED display becomes dark and the buzzer sound becomes small gradually. In such cases, replace the battery immediately.

## 2. Page2 Additional sentence

At first "IMPORTANT"

Especially, if a broken piece of the battery terminal should enter the U-WAVE-T, a failure may be caused.

## 3. Page2 Additional sentence

#### At third "IMPORTANT"

Do not connect the connecting cable forcibly in a state that the packing (No. 09GAA374) is not in the correct position on the U-WAVE-T body. Otherwise, the packing may be damaged so that a failure may be caused.

Thank you.

Marianne Bosley American TCB Inc. Direct 717-676-3203