Date: October 16, 2014

Applicant: Loopcomm Technology, Inc.

FCC ID: VYTLP2596K

Correspondence Reference Number: 183823 Form 731 number: TC730034

Change of software/firmware:

Firmware version: 1.1.1 = > 1.1.5.1

1. removed : Regulatory domain

2. removed: DFS control and DFS control

Before





After



