
## **Internal Photographs**

Transmitter Top



#### **Transmitter Bottom**



Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1


Trig Avionics Limited Model: TY92 Test #: 120820A

Test to: CFR47 Parts 2, 87 and RSS-141 File: Short Term Conf IntPho VZI00879 IC: 10614A-00879 FCC ID: VZI00879 SN: 0004


Date: October 25, 2012

Page 1 of 4

# Receiver Top



### Receiver Bottom



Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Trig Avionics Limited Model: TY92 Test #: 120820A

Test to: CFR47 Parts 2, 87 and RSS-141 File: Short Term Conf IntPho VZI00879 IC: 10614A-00879 FCC ID: VZI00879 SN: 0004


Date: October 25, 2012

Page 2 of 4

Digital Top



Digital Bottom



Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Trig Avionics Limited Model: TY92 Test #: 120820A

Test to: CFR47 Parts 2, 87 and RSS-141 File: Short Term Conf IntPho VZI00879 IC: 10614A-00879 FCC ID: VZI00879

SN: 0004

Date: October 25, 2012

Page 3 of 4

### Inside Case



Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Trig Avionics Limited Model: TY92 Test #: 120820A

Test to: CFR47 Parts 2, 87 and RSS-141 File: Short Term Conf IntPho VZI00879 IC: 10614A-00879 FCC ID: VZI00879 SN: 0004

Date: October 25, 2012 Page 4 of 4