
Internal Photographs

Transmitter Top



Transmitter Bottom



Rogers Labs, Inc. 4405 West 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Trig Avionics Limited Model: TY91 Test #: 120820


Test to: CFR47 Parts 2, 87 and RSS-141 File: Short Term Conf IntPho VZI00882 IC: 10614A-00882 FCC ID: VZI00882

SN: 0004


Date: September 9, 2012

Page 1 of 4

Receiver Top



Receiver Bottom



Rogers Labs, Inc. 4405 West 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Trig Avionics Limited Model: TY91 Test #: 120820

Test to: CFR47 Parts 2, 87 and RSS-141 File: Short Term Conf IntPho VZI00882 IC: 10614A-00882 FCC ID: VZI00882


SN: 0004

Date: September 9, 2012 Page 2 of 4

Digital Top



Digital Bottom



Rogers Labs, Inc. 4405 West 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Trig Avionics Limited Model: TY91 Test #: 120820

Test to: CFR47 Parts 2, 87 and RSS-141 File: Short Term Conf IntPho VZI00882 IC: 10614A-00882 FCC ID: VZI00882

SN: 0004

Date: September 9, 2012

Page 3 of 4

Inside Case



Rogers Labs, Inc. 4405 West 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Trig Avionics Limited Model: TY91 Test #: 120820

Test to: CFR47 Parts 2, 87 and RSS-141 File: Short Term Conf IntPho VZI00882 IC: 10614A-00882 FCC ID: VZI00882 SN: 0004

Date: September 9, 2012 Page 4 of 4