## External photographs of equipment under test





Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214

Revision 1


Trig Avionics Limited Model: TY91 Test #: 120820


Test to: CFR47 Parts 2, 87 and RSS-141 File: Short Term Conf ExtPho VZI00882 IC: 10614A-00882 FCC ID: VZI00882

SN: 0004

Date: October 25, 2012

Page 1 of 3





Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214

Revision 1

Trig Avionics Limited Model: TY91

Test #: 120820 Test to: CFR47 Parts 2, 87 and RSS-141


File: Short Term Conf ExtPho VZI00882

IC: 10614A-00882 FCC ID: VZI00882

SN: 0004

Date: October 25, 2012

Page 2 of 3





Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Trig Avionics Limited

Model: TY91 Test #: 120820

Test to: CFR47 Parts 2, 87 and RSS-141 File: Short Term Conf ExtPho VZI00882 IC: 10614A-00882 FCC ID: VZI00882

SN: 0004

Date: October 25, 2012

Page 3 of 3