

Test report No. : 29GE0155-HO-01-A

Page : 13 of 32 Issued date : April 14, 2009 FCC ID : VZQNRWA3

### **APPENDIX 1: Photographs of test setup**

#### **Conducted emission**





## UL Japan, Inc.

**Head Office EMC Lab.** 


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 29GE0155-HO-01-A

Page : 14 of 32 Issued date : April 14, 2009 FCC ID : VZQNRWA3

#### **Radiated emission**





### UL Japan, Inc.

**Head Office EMC Lab.** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

: 29GE0155-HO-01-A Test report No.


Page : 15 of 32 : April 14, 2009 : VZQNRWA3 **Issued date** FCC ID

# Worst Case Position (Y-axis) (with Tag) X-axis









**Head Office EMC Lab.** 


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124


Test report No. : 29GE0155-HO-01-A

Page : 16 of 32 Issued date : April 14, 2009 FCC ID : VZQNRWA3

# Worst Case Position (Y-axis) (without Tag) X-axis







**Head Office EMC Lab.** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124