
Test report No.: 31CE0283-HO-01-A

Page : 12 of 92

Issued date : December 22, 2010 FCC ID : W2Z-01000001

## **Spurious Emission (Radiated emission)**





## UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

Test report No.: 31CE0283-HO-01-A

Page : 13 of 92

Issued date : December 22, 2010 FCC ID : W2Z-01000001

## Pre-check of the worst position



## UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401