Test report No. : 11143372S-A-R1
Page : 76 of 79
Issued date : June 6, 2016
FCC ID : W2Z-01000008

# **APPENDIX 3: Photographs of test setup**

# **Conducted Emission**



**Front** 



Side

UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Test report No. : 11143372S-A-R1
Page : 77 of 79
Issued date : June 6, 2016
FCC ID : W2Z-01000008


## **Radiated Spurious Emission**



**Front** 



Rear (above 1GHz)



Rear( below 1GHz)

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Test report No. : 11143372S-A-R1
Page : 78 of 79
Issued date : June 6, 2016
FCC ID : W2Z-01000008

# **Worst Case Position**

## (module)



X-axis



Y-axis



**Z**-axis

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Test report No. : 11143372S-A-R1
Page : 79 of 79
Issued date : June 6, 2016
FCC ID : W2Z-01000008

# **Worst Case Position**

#### (Antenna)






Ant 1

Ant 0


X-axis






Ant 1

Y-axis





**Z**-axis

#### **End of Report**

### UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN