Test report No. : 10315698S-G Page : 23 of 23 : October 28, 2014 : W2Z-01000006 Issued date FCC ID

APPENDIX 3: Photographs of test setup




Photo 1




Photo 2

End of Report

UL Japan, Inc. **Shonan EMC Lab.**

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401