Test report No.
 : 11285933S-B-R2

 Page
 : 113 of 116

 Issued date
 : July 24, 2017


 FCC ID
 : W2Z-01000007

APPENDIX 3: Photographs of test setup

Conducted Emission

with Power supply





UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

 Test report No.
 : 11285933S-B-R2

 Page
 : 114 of 116

 Issued date
 : July 24, 2017

 FCC ID
 : W2Z-01000007

with Cradle






UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Test report No. : 11285933S-B-R2
Page : 115 of 116
Issued date : July 24, 2017
FCC ID : W2Z-01000007

Radiated Spurious Emission



Front



Rear (below 1 GHz)



Rear (above 1 GHz)

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

 Test report No.
 : 11285933S-B-R2

 Page
 : 116 of 116

 Issued date
 : July 24, 2017

 FCC ID
 : W2Z-01000007

Worst Case Position







End of Report

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN