Test Report No.: 10028285S-A

### **APPENDIX 3: Photographs of test setup**

### **Radiated Spurious Emission**




Photo 1




Photo 2

# UL Japan, Inc.

#### **Shonan EMC Lab.**

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN Telephone : +81 463 50 6400

Facsimile +81 463 50 6401

Test Report No.: 10028285S-A

## **Worst Case Position**

(Below 1GHz Horizontal: Y-axis / Vertical: Z-axis Above 1GHz Horizontal: Y-axis / Vertical: Z-axis)







## UL Japan, Inc.

#### **Shonan EMC Lab.**

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN Telephone : +81 463 50 6400

Facsimile +81 463 50 6401